

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School : CHRIST CENTRAL SCHOOL, MUTHOOR

- | | |
|---|--|
| <ol style="list-style-type: none"> 1. Name of the Officer 2. Location 3. Period for which the certificate is issued 4. Types of building 5. Nature of defect if any <ol style="list-style-type: none"> a) Foundation and basement b) Superstructure c) Doors and windows d) Wood work wrought and put up e) Roof f) Flooring g) Miscellaneous (Cracks if any) 6. Any Major defects notices which will render the building unsafe in any manner 7. Whether maintenance works have been done properly 8. Whether the structure is sound or not for conducting classes | <p>: ALKA . S</p> <p>: MUTHOOR</p> <p>: 2023 - 24</p> <p>: BUILDING 1 BUILDING II</p> <div style="display: flex; align-items: flex-start;"> <div style="flex: 1;"> <p>UF = 1x 26.47 x 9.34 x 3.75m
= 1x 63.51 x 9.20 x 3.75m
= 1x 26.47 x 9.90 x 3.75m
= 1x 7.20 x 7.80 x 3.75m</p> <p>SF = 1x 26.47 x 9.34 x 3.75m
= 1x 63.51 x 9.20 x 3.75m
1x 26.47 x 9.90 x 3.75m
1x 7.20 x 7.80 x 3.75m</p> <p>SF = 1x 26.47 x 9.34 x 3.75m
1x 63.51 x 9.20 x 3.75m
1x 26.47 x 9.90 x 3.75m
1x 7.20 x 7.80 x 3.75m</p> </div> <div style="flex: 1; padding-left: 10px;"> <p>UF</p> <p>1x 28.23 x 10.62 x 3.75</p> <p>1x 48.22 x 10.50 x 3.75</p> <p>1x 16.30 x 9.00 x 3.75</p> <p>1x 8.14 x 6.40 x 3.75</p> <p>SF</p> <p>1x 28.23 x 10.62 x 3.75</p> <p>1x 48.22 x 10.50 x 3.75</p> <p>1x 16.30 x 9.00 x 3.75</p> <p>1x 8.14 x 6.40 x 3.75</p> <p>SF</p> <p>1x 28.23 x 10.62 x 3.75</p> <p>1x 48.22 x 10.50 x 3.75</p> <p>1x 16.30 x 9.00 x 3.75</p> <p>1x 8.14 x 6.40 x 3.75</p> </div> </div> <p>g) Miscellaneous (Cracks if any) } NIL</p> <p>: NIL</p> <p>: Yes</p> <p>On visual observation the building is fit and sound for conducting classes during the academic year 2023-24 under normal wind and weather conditions.</p> |
|---|--|
- Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 08/09/2023 and found to be fit / unfit to conduct classes for the period 2023-24 for the reason stated above.

Place: Thiruvalla
Date: 18-09-2023

FR. THOMAS CHEMPILPARAMPIL CMI
PRINCIPAL
CHRIST CENTRAL SCHOOL
MUTHOOR, THIRUVALLA-689 107
PATHANAMTHITTA



(Seal)

Alka S
18/09/23
Assistant Engineer
THIRUVALLA

Alka S
MANAGER
CHRIST CENTRAL SCHOOL
MUTHOOR, TIRUVALLA - 689 107